SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 5 W

SECTION 3 CORNER N 1/16 "C"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1" x 30" Alum. Pipe by single proportionate method. MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
24" Fir Stump	N 88° E	1.1	--	X	X	--
18" Fir	N 5° W	9.7	--	X	X	--

IDENTIFIED ON PHOTO: NO

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Hazel nut, Oceanspray & blackberries

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 60° W ON MINUS (-) 46 %

FROM CORNER -

NORTH: + 18% Logged

SOUTH: - 30 Logged for 100' then virgin timber on East side & logged on West side.

EAST: + 36 Logged

WEST: - 43 Logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Robert Batts DATE: 11-10-60

~~ENGINEER - SURVEYOR~~
Instrumentman

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/105-A1