SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 5 W

SECTION 3 CORNER Prop. Cor.

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1" x 30" Alum. Pipe MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
8" Fir	East	1.4	--	X	X	--
8" Fir	S 28 W	8.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Field fern & 2nd gr.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 80° W ON MINUS (-) 36 %

FROM CORNER —

NORTH: - 15% 100' House

SOUTH: + 15% Logged

EAST: + 35% Logged

WEST: - 35% Logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Robert Baker ~~ENGINEER-SURVEYOR~~ Instrumentman DATE: 11/10/60

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/105-AZ