


# PUBLIC LAND CORNERS

SPRINGFIELD  
SURVEY FILE

MEYER RAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 5 W  
SECTION 8 CORNER SW  
COUNTY Douglas OREGON



### GLO SURVEY RECORD

DATE: 1855  
CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION)

Gone

### ACCESSORIES:

	BEARING-	LINKS-	FEET-	
60" Fir	N 12° E	26	17.2	Now badly burned large stump. No scribing visible.
18" Laurel	S 30° W	22	14.5	Fd 24" Laurel standing. Two old face holes. No scribing visible.
18" Oak	N 33° W	83	54.8	Gone
No tree in Section 17				

C. Thomson SURVEY RECORD  
DATE: 1955

PRESENT CONDITION:

Fd. 18" Laurel	S 50° W	14.5		
Fd. Fir Stp.	N 12° E	17.1		
Set New BT's				
14" Fir	S 34° E	57.3'		Fd 18" Fir Healed over.
8" "	S 11° W	30.4'		Fd 10" Fir " "

CORNER SET: 1/2" monel pipe set by brg. & distance from MAG. DECL.: 20°

original NE & SW BT distance only.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 12° E	17.2	1855	Large Fir Stump
S 63° W	14.5	"	24" Laurel
S 31° E	57.1	1955	18" Fir
S 21° W	30.4	"	10" Fir

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
70" Burned Fir Stump	N 3° E	13.9	X	X	X	-
18" Fir	S 31° E	56.2	-	X	X	-
"X" Rock out crop	S 65° W	3.0	-	-	-	-
10" Fir	S 21° W	32.1	-	X	X	-
22" Laurel IDENTIFIED ON PHOTO:	S 63° W	13.2	X	X	X	-

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Rock out crops and grass.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 60° E ON MINUS (-) 78 %

NORTH: + 42% Logged

SOUTH: - 30% "

EAST: - 65% " 150' ravine C - South

WEST: + 70% "

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: \_\_\_\_\_

BY: Robert Banta DATE: May 2, 1960

~~ENGINEER~~ SURVEYOR  
INSTRUMENT M.N.

ASSISTED BY: \_\_\_\_\_

UNDER THE SUPERVISION OF:

COPIES SENT TO: \_\_\_\_\_

SEAL PAGE 3

CS 53/105-A3