


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

MEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 5 W
SECTION 8 CORNER W 1/4
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1855

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
40" Fir	S 85° E	21	13.9	Round 50" Fir face burned out. No scribing visible.
48" Fir	S 38° W	75	49.5	Found badly decayed Fir stump. Negative "BT" slab nailed to stump.

Wm. C. Thomson SURVEY RECORD

DATE: 1955

PRESENT CONDITION:

Found: 50" Fir S 85° E 13.9'	Found
Fir Stp. N 9° W 54.8'	Found
Set: 5/8" rod and 2 BT's	
14" Fir S 60° W 24.9'	Found scribed "BT"
18" Fir N 30° W 27.0'	Found scribed "BT"

CORNER SET: 5/8" rod as set in 1855

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
S 61° W	24.9	1955	16" Fir Face measurement
N 31° W	27.0	1955	20" Fir Face measurement

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
10" Fir	S 35° E	53.8	-	X	X	-
20" Fir	N 31° W	26.9	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: hazelnut, oceanspray, fern.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 45 %

NORTH: Level Logged on East side and virgin on West side.

SOUTH: Level Logged.

EAST: 45% 30' Fence cor. Logged.

WEST: 45% Logged on South side and virgin on North side.

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Robert Banta DATE: May 2, 1960

Instrumentman

ASSISTED BY:

UNDER THE SUPERVISION OF:

COPIES SENT TO:

CS S3/105-A4