


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22S RANGE 5W
SECTION 23 CORNER S₄
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1855
CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

BEARING-	LINKS-	FEET-	
40" Fir N 02° E	79	52.1	Fd. 48" Fir Bark scribing partly visible
4" Fir S 42° W	44	29.0	Fd. 36" Fir stp. Scribing "S" visible.

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: Found 1" Iron rod marked "S" on top MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 3° E	52.1	GLO	48" Fir Slope Face Measurement
S 43° W	30.0	GLO	36" Fir stp. Face Measurement

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
22" Fir	N 31° E	30.0	-	X	X	-
36" Fir Stump	S 43° W	28.8	X	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Hazelnut, Ocean Spray, Bracken Fern and Salal
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) N 35° W ON MINUS (-) 66 %

NORTH: - 55% 110' Creek C - N 35° E. Logged on West side & virgin on East side.

SOUTH: + 40% for 50' then level. Logged

EAST: + 28% Logged on South side and virgin on North Side.

WEST: - 45% for 80' Creek C - N 35° E. Logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: *Robert B. [Signature]* DATE: April 22, 1960
ENGINEER & SURVEYOR
Instrumentman

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

C.S 53/105-A6