


# PUBLIC LAND CORNERS

SPRINGFIELD  
 SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 22S RANGE 5W  
 SECTION 23 CORNER W $\frac{1}{2}$   
 COUNTY Douglas OREGON

#110



**GLO SURVEY RECORD**

DATE: 1855

CORNER Post PRESENT CONDITION: Gone

**ACCESSORIES:**

	BEARING-	LINKS-	FEET-	
5" Blk. Oak	N 28° E	9	5.9	Gone
4" Fir	S 57° W	12	7.9	18" Fir Upper scar has been chopped out and scribing "S" visible.

**SURVEY RECORD**

DATE:

PRESENT CONDITION:

CORNER SET: Corner point falls on large root. Drove "W" MAG. DECL.: 20° nail for corner.

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY-	
S 57° W	7.9	GLO	18" Fir Face measurement

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
16" Fir	N 63° E	17.8	-	X	X	-
18" Fir	S 57° W	7.7	X	X	X	-

IDENTIFIED ON PHOTO:

**INFORMATION ON LOCATION OF CORNER AS NOW SET:**

GROUND COVER: Fern, Hazelnut, Willow and Dogwood

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 11 %

FROM CORNER | NORTH: - 11% logged  
 | SOUTH: + 12% "  
 | EAST: Level 18' N & S Fence line, then open field  
 | WEST: Level Logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Robert Carter DATE: April 22, 1960

ENGINEER SURVEYOR  
 Instrumentman

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

CS 53/105-A7