

# PUBLIC LAND CORNERS


SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 2 W

SECTION 31 CORNER SW

COUNTY Douglas OREGON



#3

## GLO SURVEY RECORD

DATE: 1894

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

### ACCESSORIES:

	BEARING-	LINKS-	FEET-	
16" Cedar	N 9° 30' E	42	27.72	O. K.
60" Fir	S 57 E	38	22.9	Now a 66" Fir Stump.
9" Alder	S 35 W	6	3.96	Gone

Meyerhaeuser Co. SURVEY RECORD  
DATE: 1956

Pipe - 5/8" X 2.8 - For Corner.  
" - 3/4" X 4" - Marker

S 63 E - 23.9 - 50" Fir

N 10 E - 28.0 - 26" Cedar B. T.

PRESENT CONDITION:

CORNER SET:

MAG. DECL.: 20° E

### BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 10 E	27.1	1963-W.Co.	Measured to "W" nail; original cedar B. T.
S 58 E	22.9	" "	" " " " ; 66" Fir Stump.

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
66" Fir Stump	S 58 E	22.9	X	X	X	-
26" Hem.	S 50 W	18.1	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logged S. E. side of corner; Timber to N. W.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 27° W-100' ON MINUS (-) 30 %

Corner is on Southern Tip of N. & S. cutting line.

NORTH: + 12% - 200'

SOUTH: - 22% - 200'

EAST: - 16% - 180'

WEST: + 6% - 50' over Ridge.

FROM CORNER

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: M. D. Hale DATE: May 7, 1963

~~WYERHAEUSER~~ - SURVEYOR

ASSISTED BY: H. E. Case

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/106-1