


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 23S RANGE 2W
SECTION 32 CORNER E 3
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
30" Fir	S 48 E	104.9	X	X	X	---
34" Fir	S 2 E	119.0	----	X	X	---

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Red rock ridge top
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) west ON MINUS (-) 30 %

NORTH: 33' level to edge ridge - drops 70'
SOUTH: -5% - current logging to west
EAST: +10% 18' to edge of ridge - drops 70'
WEST: -30% 55' then drops along edge of ridge. Current logging

FROM CORNER |

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: 1894
CORNER Stone 16" x 10" x 6"

No trace of the original stone has been found

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
26" Fir	S 48 E	159	104.9	Found 30" Fir - 2 faces - opened upper face and found scribing
36" Fir	S 10 W	148	97.7	40" down Fir - 2 faces grown over. Tree has slid out of root hole 10' to SW

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: 3" square Fir stake ^{1" Aluminum Pipe} set by distance MAG. DECL.: 20°
and bearing from SE Bt. distance and bearing to root hole SW Bt. ok.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 48 W	104.9	1894	Bearing from Bt. to corner point - distance from face
S 10 W	97.7	1894	Bearing and distance from corner to root hole

PAGE 1

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

By: Allen McChesney DATE: October 15, 1964
~~ENGINEER/SURVEYOR~~
LAND AGENT

ASSISTED BY:

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL PAGE 3

CS 53/106-2

5
53/106