6

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 2 W

SECTION 33 CORNER S 1/16 = "K"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1" aluminum pipe and mound MAG. DECL.:

of stone by single proportionate method

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
6" Fir	N 77° E	8.0	-----	X	X	-----
38" Fir	N 21° W	22.4	-----	X	X	-----

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER:

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (-) %

FROM CORNER I

NORTH: 136' to post and plate on south side of Bohemia Fire road

SOUTH:

EAST:

WEST:

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Robert Barta DATE: October 28, 1964
ENGINEER - SURVEYOR

ASSISTED BY: Glen McChesney

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/106-5