SPRINGFIELD

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 23S RANGE 3 W

SECTION 28 CORNER C 1/4 = Point "I"

COUNTY LANE & DOUGLAS COUNTY LINE OREGON

GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1/2" x 35" GALV I PIPE BY INTERSECTION METHOD MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG.B.T.	"W" NAIL	PLATE	BRASS DISC
36" fir stump	N 62° W	14.1		X	X	
65" fir stump	N 12° W	57.7		X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: LOGGED

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 25° E ON MINUS (-) 60 %

for 8' to small creek course N 70° E

FROM CORNER I

NORTH: - 60° for 8', small creek

SOUTH: + 60% for 40' to North edge "W.A.W." dirt road

EAST: - 20% for 50'

WEST: Level for 25' to small creek, thence +35% for 25'

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: M.D.HALE DATE: MARCH, 1959
~~ENGINEER~~ - SURVEYOR

ASSISTED BY: H. E. CASE
W. W. DIXON

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

21

CS 53|107-2