PUBLIC LAND CORNERS

SPRINGFIELD SURVEY LIBRARY

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 23 S RANGE 3 W

SECTION 28 CORNER CW 1/16 = Point "J"

COUNTY LANE & DOUGLAS COUNTY LINE OREGON

GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1/2" x 35" Galv. I. Pipe by Single proportionate method MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
30" Hemlock stump	S 34° E	24.6		x	x	
30" Hemlock Stump	N 43° W	17.0		x	x	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Reproduction, sapling & 2nd growth fir & hemlock

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 "PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 75° E ON MINUS (–) 43 %

FROM CORNER –

NORTH: - 7%

SOUTH: Level 50'

EAST: - 30%

WEST: + 30%

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: G.C.9

BY: M. D. HALE DATE: MARCH 31, 1959

~~ENGINEER~~ – SURVEYOR

ASSISTED BY: H. E. CASE
W. W. DIXON

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

11

CS 53/107-3