


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH



TOWNSHIP 23 S RANGE 3 W

SECTION 28 CORNER E 1/4

COUNTY LANE & DOUGLAS COUNTY LINE OREGON

GLO SURVEY RECORD

DATE: 1882

CORNER # 5" Hemlock

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Not Found

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
5" hemlock	East b	18		Not Found
6" Hemlock	West	30		Not Found

SURVEY RECORD

DATE: _____

PRESENT CONDITION: _____

CORNER SET: Set 1/2" x 35" Gal I Pipe by single proportionate method MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
<u>XB</u> 30" hemlock stump	S 16° W	<u>53.3</u> 322		x	x	
36" Cedar Stump	S 9° E	132.0		x	x	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logged, some fern

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 65 %

NORTH: + 14% for about 120'

SOUTH: - 10% for 135' to small creek, course NE

EAST: - 63% for 70'

WEST: + 65% for 70'

FROM CORNER |

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: M. D. HALE DATE: MARCH, 1959
~~ENGINEER~~ - SURVEYOR

ASSISTED BY: H. E. CASE
W. W. DIXON

COPIES SENT TO: _____

UNDER THE SUPERVISION OF:

CS 53/107-4

14