


SPRINGFIELD
 SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 3 W
 SECTION 31 CORNER SW
 COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20 E

	BEARING	FEET	ORIG. B. T.	"W" NAIL	PLATE	BRASS DISC
30" Fir stump	N 21 E	175.6	(Resurvey) X	X	X	--
60" Fir Stump	N 64 E	169.6	(Resurvey) X	X	X	--
24" Fir	S 59 W	54.2	--	X	X	--
5" Chinquapin	S 43 E	8.5	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Fir reproduction, salal, & bracken fern

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 5 W ON MINUS (-) - 48 %

NORTH: + 31% for 150' to bench

SOUTH: -48% for 150' breaks to gentle slope

EAST: +47% for 100' breaks steeper

WEST: -35% for 200'

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Bruce Malcom DATE: January 17, 1962

ENGINEER SURVEYOR
 Assistant Forester

ASSISTED BY: Bob Duncan

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: 1950

CORNER Iron post 3" by 3' with brass cap

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Iron post & cap present also original stone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
30" Fir	N 21 E	266		30" fir is now a stump, scribing visible
60" Fir	N 63 45' E	257		60" fir is now a stump, scribing visible

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET:

MAG. DECL.:

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N 21 E	175.6	G. L. O. (Resurvey) B. T.
N 63 45' E	169.6	G. L. O. (Resurvey) B. T.

PAGE 1

C 553/107-10

61