


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 3 W
 SECTION 36 CORNER S.E.
 COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
40" Fir stump	N 47 E	13.7	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logged

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 25 E ON MINUS (-) 76 %

NORTH: +56%

SOUTH: -68% - (20' center of cat skid road)

EAST: -30%

WEST: +30% - 100'

FROM CORNER -

GLO SURVEY RECORD

DATE: 1882

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
26" Fir	N 60 E	22	14.5	Now a stump
6" V.M.	S 25 E	44	29.0	Gone
6" V.M.	S 20 W	23	15.2	Gone
26" Fir	N 45 W	13	8.6	Now a stump

W. Co. **SURVEY RECORD**
 DATE: 1954

Set: 1/4" G.I.P.
50" Fir B.T. N 45 W 8.6
50" Fir B.T. S 47 E 13.7

PRESENT CONDITION:

Found 1963
Now a stump
Destroyed by logging

CORNER SET: Stake

MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 45 W	8.6	G.I.P.	50" Fir B.T. (Distance to "W" nail)

PAGE 1

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: M.D. Hale DATE: 5-6-63

~~ENGINEER~~ SURVEYOR

ASSISTED BY: H. E. Case

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/107-11