


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24S RANGE 3W
SECTION 4 CORNER NE
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
46" Fir	N 12° E	17.7	X	X	X	---
62" Fir	N 58° W	33.9	---	X	X	---
36" Fir	S 39° W	67.8	---	X	X	---
36" Fir (1946 Plate)	S 17° W	7.3	X	X	X	---

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Wind throw to be logged 1965
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 50 %

NORTH: _____
SOUTH: _____
EAST: _____
WEST: _____

FROM CORNER I

GLO SURVEY RECORD				PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
DATE: <u>1882</u>				
CORNER <u>Post</u>				<u>No evidence</u>
ACCESSORIES:				
	BEARING-	LINKS-	FEET-	
36" Spruce	S 70° E	35	23.10	<u>No evidence - probably Douglas Fir</u> <u>36" D. F. now snag rootwad, corner pt. of face</u> <u>40" D. F. Windfall scribing on bark visible</u> <u>46" D. F. Snag bark sloughed away - no scribing</u>
36" Spruce	S 20° W	11	7.3	
36" Douglas Fir	N 60° W	5	3.30	
40" Douglas Fir	N 10° E	70	46.2	
SURVEY RECORD				
DATE: _____				PRESENT CONDITION: _____

CORNER SET: None MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:			
BEARING-	FEET-	SURVEY -	
S 17° W	7.3	1882	<u>Measured to bark</u>

PAGE I

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK: _____

BY: D. H. Jordan DATE: 12/16/64
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: Harley Case

COPIES SENT TO: _____

FILED
RECEIVED

SEAL
MAR 12 1965
PAGE 3

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

CS 53/107-12