


# PUBLIC LAND CORNERS

WEVERMAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 236 RANGE             
 SECTION 14 CORNER             
 COUNTY DOUGLAS OREGON



COTTAGE GROVE NOOK #6

## GLO SURVEY RECORD

DATE: 1882  
 CORNER POST

### ACCESSORIES:

	BEARING-	LINKS--	FEET-
24" FIR	S 45° E	25	
36" FIR	N 45° E	4	

PRESENT CONDITION - (SEE PAGE 2 IF NEEDED FOR EXPLANATION)

POST CONE, AT INTERSECTION OF S-W & N-E QUARTER  
 LINE BLAZES, FOUND 1914-16 BLAZES, CRUISER  
 MARK "W" ON PIECE FIR BARK EXPOSED TOP OF 36"  
 FIR STUMP; ALSO BLUE PLATE ON THIS STUMP IN  
 MARKED S 45° E 29 FT. ON SLOPE OF 100 FT.  
 DIST. 27-23S-3W  
 CRUISER MARK "L" ON DOWN 16" NAIL

36" FIR STUMP S 47 1/2° E 15.5', WITH GRASS TO  
 EVIDENCE, NO AGE OR SCRIBING FOUND, PROBABLY  
 RUBBED OFF.  
 HOME, CAT ROAD AT THIS POSITION.

## SURVEY RECORD

DATE:           

PRESENT CONDITION:           

CORNER SET:            DROVE 2" x 35" PIPE 10" INTO            MAGNETIC DECLINATION:            20° E

### BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	
S 47 1/2° E	15.5	PROBABLE ORIGIN: BT 36" FIR STUMP

CS 53/107-18

Tree 1

Page 1

ACCESSORIES ADDED THIS DATE:

	BEARING-	FEET	ORIG. BT	"W"-NAIL	PLATE	BRASS DISC
36" FIR STAMP ASSUMED ORIGINAL	S 15° E			X	X	
50" FIR STAMP	N 15° E			X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

DESCRIPTION OF GROUND COVER AND GROUND SLOPE AT CORNER: SW NE 1/4 2-10-10

ALL IN FEET SW 1/4 1-10-10 100' N 15° E 100' E 100' S 15° W 100'

FROM CORNER ~~100' SW 1/4 1-10-10~~ 100' N 15° E 100' E 100' S 15° W 100'

SOUTH: \_\_\_\_\_

EAST: \_\_\_\_\_

WEST: \_\_\_\_\_

WORK DONE FOR W. T. CO.

BY: Hale DATE: MARCH 9  
ENGINEER - SURVEYOR

ASSISTED BY: WILLIAM WARNER UNDER SUPERVISION OF \_\_\_\_\_

COPIES SENT TO: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_