


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 23S RANGE 4W
SECTION 24 CORNER N $\frac{1}{2}$
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE: 3-12-57
Set stake for corner

MAGNETIC DECLINATION 20°E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
<u>32" Fir</u>	<u>N4°W</u>	<u>13.0</u>		<u>X</u>	<u>X</u>	
<u>26" Fir</u>	<u>S28°E</u>	<u>9.1</u>		<u>X</u>	<u>X</u>	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

NORTH: _____

SOUTH: _____

EAST: _____

WEST: _____

FROM CORNER -

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: C.G. #9

BY: Marion D. Hale DATE: March 12, 1957
~~ENGINEER~~ SURVEYOR

ASSISTED BY: D. Warner
G. Waller

COPIES SENT TO: _____

UNDER THE SUPERVISION OF:

SEAL PAGE 3

GLO SURVEY RECORD				PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
DATE:	NUMBER	STONE	PRESENT CONDITION:	
		Stone		Not Found
ACCESSORIES:				
BEARING-	LINKS-	FEET-		
<u>14" Fir</u>	<u>N55°E</u>	<u>24</u>		<u>chopped to show scribing</u>
<u>10" Fir</u>	<u>S64°W</u>	<u>31</u>		<u>gone</u>
WICO SURVEY RECORD				PRESENT CONDITION:
DATE:				
<u>1944</u>				
<u>24" Fir N55°E 15.8 to Brass plate</u>				<u>o.k.</u>
<u>24" Fir S28°E 10.0 to Brass plate</u>				<u>o.k.</u>

CORNER SET: Set stake for corner MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
<u>N55°E</u>	<u>15.8</u>	<u>GLO</u>	<u>original BT, 24" Fir</u>

CS 53/108-3