


# PUBLIC LAND CORNERS

SPRINGFIELD  
SURVEY FILE

MEYERHAEUSER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 4 E  
SECTION 14 CORNER SE  
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
24" Fir (Haines BT 1963)	N 11 E	36.8	-	X	X	-
12" Fir (Haines BT 1963)	N 72 W	7.6	-	X	X	-
20" Fir (Haines BT 1963)	S 56 W	62.0	-	X	X	-
24" Fir (Haines BT 1963)	S 22 E	26.5	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Surrounded by uncut 2nd growth fir.  
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
SLOPE FACES (GIVE BEARING IN DEGREES) N 45 W ON MINUS (-) 24 %

NORTH: -7% Uncut 2nd Growth Fir

SOUTH: +7% Uncut 2nd Growth Fir

EAST: +20% Uncut 2nd Growth Fir

WEST: -10% Uncut 2nd Growth Fir

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Wilt DATE: May 13, 1964  
ENGINEER - SURVEYOR

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL PAGE 3

## GLO SURVEY RECORD

DATE: \_\_\_\_\_

CORNER \_\_\_\_\_

### ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

## Willford Haines SURVEY RECORD

DATE: 5/22/64

PRESENT CONDITION:

24" Fir	N 12 E	37.6	Good - Verified
12" Fir	N 72 1/2 W	8.4	Good - Verified
20" Fir	S 56 W	63.0	Good - Verified
24" Fir	S 21 E	27.5	Good - Verified

CORNER SET: Round mound of stone and 2" iron stake MAG. DECL.: 20

### BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 11 E	37.6	1963	To center of tree - 24" Tree
N 72 W	8.2	1963	To center of tree - 12" Tree
S 56 W	63.0	1963	To center of tree - 20" Tree
S 22 E	27.8	1963	To center of tree - 24" Tree

CS 53/108-4