


# PUBLIC LAND CORNERS

SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 4 W  
SECTION 14 CORNER SW  
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
Fir (1963 Doug. Co. BT)	N 56° E	21.4	--	X	X	--
6" Fir ( " " " " )	S 60° E	10.2	--	X	X	--
5" Fir ( " " " " )	N 47° W	12.2	--	X	X	--
50" Fir stump ("W" nail center of top)	S 47° W	34.3	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: 25 - year old fir reproduction

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 20° W ON MINUS (-) 65 %

NORTH: - 68% - Logged E & W - 20 year old fir reproduction

FROM CORNER ↓

SOUTH: + 70% - Logged West; uncut O.G. fir East

EAST: - 3% - Logged North; " " " South

WEST: 0% for 40', thence descend to Creek bearing SW; Logged N & S

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Hilt DATE: 4/5/63

ENGINEER/SURVEYOR  
Land Agent

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

## GLO SURVEY RECORD

DATE: 1884

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

## ACCESSORIES:

	BEARING-	LINKS-	FEET-	
10" Fir	S 40° W	43	28.4	No trace
24" Fir	S 66° E	30	19.8	" "
8" Fir	N 21° E	15	10.0	24" Fir, uprotted, face opened and charred but good scribing visible
12" Laurel	N 53° W	42	27.7	No trace

Douglas Co. SURVEY RECORD  
DATE: March 1963

PRESENT CONDITION:

5" D. Fir	S 80° W	5.4'		Good
6" D. Fir	N 46° W	12.4'		"
8" D. Fir	N 55° E	21.6'		"
10" D. Fir	S 63° E	10.4'		"

CORNER SET: (Found Douglas Co. Brass Cap & "T" iron stake) MAG. DECL.: 20°

## BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 21° E	9.9	1884	Measured from approx. original position
S 85° W	5.8	1963	" to face
N 47° W	12.2	"	" " "
N 56° E	21.4	"	" " "
S 60° E	10.2	"	" " "

PAGE 1

CS 53/108-5