

# PUBLIC LAND CORNERS


SPRINGFIELD  
 SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 4 W

SECTION 24 CORNER N 1/4

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
24" Fir	N 55° E	15.8	X	-	X	-
24" Fir	S 28° E	10.0	-	-	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: \_\_\_\_\_  
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
 SLOPE FACES (GIVE BEARING IN DEGREES) \_\_\_\_\_ ON MINUS (-) %

NORTH: \_\_\_\_\_  
 SOUTH: \_\_\_\_\_  
 EAST: \_\_\_\_\_  
 WEST: \_\_\_\_\_

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: \_\_\_\_\_

BY: Ruby Carter DATE: April, 1944  
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF \_\_\_\_\_

ASSISTED BY: Fred G. Brown

COPIES SENT TO: \_\_\_\_\_

SEAL PAGE 3

CSS3/108-6

**GLO SURVEY RECORD**

DATE: \_\_\_\_\_  
 CORNER Stone

**ACCESSORIES:**

	BEARING-	LINKS-	FEET-	
14" Fir	N 55° E	24		Chopped out to show scribing
10" Fir	S 64° W	31		Down & rotten

**SURVEY RECORD**

DATE: \_\_\_\_\_

**PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**PRESENT CONDITION:** \_\_\_\_\_

CORNER SET: from NE original MAG. DECL.: \_\_\_\_\_

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY -
N 55° E	15.8	Glo