

PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE


WEYERHAEUSER TIMBER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 4 W

SECTION 24 CORNER S 1/2

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
40" Fir	N 28° E	21.8	X	-	X	-
70" Fir	N 53° W	23.8	-	-	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) _____ %

NORTH: _____

SOUTH: _____

EAST: _____

WEST: _____

FROM CORNER

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Leslie Calder DATE: April, 1944
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF

ASSISTED BY: Jack Carlson

F. G. Brown

Percy Dodd

COPIES SENT TO: _____

GLO SURVEY RECORD

DATE: _____

CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
36" Fir	N 28° E	33		OK on bark
40" Fir	S 12° E	18		Down - scribing on bark

SURVEY RECORD

DATE: _____

PRESENT CONDITION: _____

CORNER SET: Stake

MAG. DECL.: _____

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 28° E		GLO	Standing
S 12° E		"	Down

PAGE 1

SEAL

PAGE 3

CS 53/108-7