SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 23S RANGE 4W

SECTION 25 CORNER E¼

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

BEARING-	LINKS-	FEET-

SURVEY RECORD

DATE:

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION:

CORNER SET: Pipe MAG. DECL.:

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
60" Fir Stump	N 54° W	33.5		X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER:

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (-) %

FROM CORNER -

NORTH:

SOUTH: 273' Tag on Harness Mt. 300 line.

EAST:

WEST:

WORK DONE FOR W. T. CO.: FIELD NOTES IN BOOK:

BY: Wm. Miles ~~ENGINEER - SURVEYOR~~ DATE: 8-26-57

ASSISTED BY: V. Friling

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/108-9

4