

6

PUBLIC LAND CORNERS


SPRINGFIELD
SURVEY FILE

WYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 4 W

SECTION 36 CORNER W 1/4

COUNTY DOUGLAS OREGON



ACCESSORIES ADDED THIS DATE: 7-23-59

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
14" Fir	N 82° E	24.1		X	X	
40" Fir	N 35° W	4.0	X	X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Timber, Salal & Ocean Spray

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) on ridge top ON MINUS (-) %

NORTH: Level Logged on East side & virgin on West side

SOUTH: Level Logged on East side & virgin on West side

EAST: + 4% Logged

WEST: - 18% Virgin Timber

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: WM. WILT DATE: 7/23/59

ENGINEER-SURVEYOR

ASSISTED BY: ROBERT BARTA

UNDER THE SUPERVISION OF

COPIES SENT TO:

SEAL

PAGE 3

GLO SURVEY RECORD

DATE: 1897

CORNER Post _____ PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

GONE

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
50" Fir	S 34° E	9	5.9	54" Fir - Healed Face
36" Fir	N 35° W	9	5.9	40" Fir - Scribing visible

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1/2" x 30" G.I.P. MAG. DECL.: 20°

Fd 2" x 2" x 3" Fir Post

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S 34° E	5.9	GLO	54" Fir
N 35° W	5.9	GLO	40" Fir

PAGE 1

CS 53/108-15

SEE 1963 NOTES ATTACHED