


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 23 S RANGE 4 W
SECTION 36 CORNER W 1/4
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE: 10/9/63

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	'W' NAIL	PLATE	BRASS DISC
50" Fir	S 37 E	3.0	X	X	X	---

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal and Ocean Spray

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (-) 1/2

NORTH: Level - Logged to East and to West

SOUTH: " " " " plate on North side rock road reads: "635' North to 1/4 Cor."

EAST: + 4% Logged

WEST: - 18% "

FROM CORNER -

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: *Alan M. Cheney* DATE: 10/9/63
ENGINEER SURVEYOR
Land Agent

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: 1879

CORNER post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace of original

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
50" Fir	S 34 E	9	5.9	54" Fir - healed face
36" Fir	N 35 W	9	5.9	40" Fir - Scribing visible

Weyerhaeuser Company SURVEY RECORD
DATE: 7/23/59

PRESENT CONDITION:

Drove 1/2"x30" G.I.P.	Found
14" Fir N 82 E 24.1 Plate W nail	Now blown down
40" Fir N 35 W 4.0 " "	OK

CORNER: 1/2" pipe as set by W. Co. 1959

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
S 34 E	5.9	GLO	
N 35 W	4.0	"	Face

CS 53/108-16