


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24S RANGE 3W
SECTION 1 CORNER NW
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE: Sept. 25, 1964 MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
11" Hemlock	S19°45'W	18.1	-	X	X	-
30" Cedar	S77°15'W	25.8	X	X	X	-
9" Hemlock	N35°E	10.0	-	X	X	-
24" Cedar	N56°E	53.7	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Blowdown heavy
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

NORTH: _____
FROM CORNER - SOUTH: _____
EAST: _____
WEST: _____

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK: _____

BY: Jordan D.H. DATE: 9-25-64
ENGINEER - SURVEYOR

ASSISTED BY: Jack Wilson

COPIES SENT TO: _____

UNDER THE SUPERVISION OF:

SEAL PAGE 3

GLO SURVEY RECORD		PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)	
DATE: <u>1882</u>			
CORNER <u>10" Hemlock</u>		<u>24" tree wind thrown faces grown over</u>	
ACCESSORIES:			
	BEARING-	LINKS-	FEET-
<u>6" Hemlock</u>	<u>N60°W</u>	<u>14</u>	<u>9.2</u>
<u>6" Hemlock</u>	<u>N30°E</u>	<u>39</u>	<u>25.7</u>
<u>24" Cedar</u>	<u>S 1°E</u>	<u>32</u>	<u>21.1</u>
<u>20" Cedar</u>	<u>S70°W</u>	<u>49</u>	<u>32.3</u>
			<u>No evidence</u>
			<u>No evidence</u>
			<u>12" Snag-scribing visible</u>
			<u>24" Cedar standing face chopped out</u>
			<u>scribing visible</u>
SURVEY RECORD		PRESENT CONDITION:	
DATE: _____		_____	

CORNER SET: None MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:			
BEARING-	FEET-	SURVEY -	
<u>N77°W</u>	<u>26.3</u>	<u>1882</u>	<u>Distance measured to face</u>
<u>S1°E</u>	<u>21.1</u>	<u>1882</u>	<u>Distance measured to face</u>

CS 53/111-2