

SPRINGFIELD
SURVEY FILE


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 2 CORNER W 1/4

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
44" Fir stump	S 39° W	31.4	—	X	X	—
32" Fir stump	N 37° W	17.0	—	X	X	—

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logged

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 70° W ON MINUS (-) 78 %

NORTH: -25% for 25 Ft. Springbranch, thence 40% 200'

SOUTH: +25% 50'

EAST: + 82% 100' (228' to plate on 44" Fir stump along dirt spur road station 7+67.0

WEST: -76% 100'

FROM CORNER

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: M. D. Hale DATE: 5-3-63

ASSISTED BY: H. E. Chase

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: 1883

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
24" Fir	N 34° E	76		Gone
10" Fir	S 39° W	51		Gone
				See page 2

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: 1" x 30" Aluminum Pipe

MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/111-4