SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24S RANGE 3W

SECTION 5 CORNER Ck

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 7/8" x 38" drill steel MAG. DECL.: 20°E

by transit intersection

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
37" Fir	N 42° W	29.8		X	X	#243
44" Fir	S 73° E	24.3		X	X	#243

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: O.G. Fir and Hemlock Sapling

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 23° E ON MINUS (–) 60 %

FROM CORNER –

NORTH: + 60% for 50'

SOUTH: - 55% for 50'

EAST: - 13% for 100'

WEST: + 32% for 100'

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: Sutherlin 67

BY: Morris D. Hall ENGINEER – SURVEYOR DATE: April 11, 1960

ASSISTED BY: H. E. Case
W. W. Dixon

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS. 53/111-7