SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24S RANGE 3W

SECTION 5 CORNER CE 1/16

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1/2" x 36" G. I. Pipe Transit survey MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
34" Fir	S 33° W	28.9	-	X	X	#243
35" Fir	N 13° E	8.5	-	X	X	#243

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: O.G. Fir

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 10° E ON MINUS (-) 30 %

FROM CORNER

NORTH: + 22% for 70'

SOUTH: - 30% for 70'

EAST: - 13% for 70'

WEST: + 12% for 50'

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: Suth. 67

BY: [signature] DATE: April 14, 1960

ENGINEER - SURVEYOR

ASSISTED BY: H. E. Case
W. W. Dixon

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/11-8