


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24S RANGE 3W
SECTION 5 CORNER E 1/16 "A"
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
40" Fir	N 87° W	65.5		X	X	#243
42" Fir Stump	S 28° E	72.8		X	X	#243

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) N 45° E ON MINUS (-) 30 %

Logged - Sword Fern and Sapling Hemlock

NORTH: - 26%

SOUTH: + 25%

EAST: - 20%

WEST: + 15%

GLO SURVEY RECORD			PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
CORNER	DATE: _____		
ACCESSORIES:			
BEARING-	LINKS-	FEET-	
SURVEY RECORD			PRESENT CONDITION: _____
DATE: _____			

CORNER SET: 1/2" x 30" Galvanized I. Pipe MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

WORK DONE FOR W. T. CO. : _____ FIELD NOTES IN BOOK: Such. 67

BY: _____ DATE: April 27, 1960

ENGINEER - SURVEYOR

ASSISTED BY: H. E. Case
W. W. Dixon
B. Tolman

COPIES SENT TO: _____

UNDER THE SUPERVISION OF: _____

CS 53/111-9