

SPRINGFIELD
SURVEY FILE


PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 5 CORNER W 1/4

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1950

CORNER Pipe & Brass cap

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Okay

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
10" Fir	N 77-1/4° E	8	5.28	Okay
9" Fir	N 32° W	33	21.78	Okay

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: Brass Cap

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 30° W	21.7	GLO	9" Fir Measured to face
N 77° E	4.7	"	12" Fir " " "

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
8" Fir	S 36° E	16.2				
1 1/4" Fir	N 18° W	18.9				

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sapling, samll poles, bracken fern & salal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) 57° W for 50' ON MINUS (-) 45 %

FROM CORNER -

NORTH: + 45% for 150'

SOUTH: - 15% for 60'

EAST: + 34% for 150'

WEST: - 45% for 60' to swale

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: William W. Hule DATE: 2-24-60

~~ENGINEER~~ SURVEYOR

ASSISTED BY: H. E. Case

W. W. Dixon

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS. 53/111-10