SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W
SECTION 6 CORNER E 1/16
COUNTY Douglas OREGON



GLO SURVEY RECORD
DATE:
CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: Hemlock Post. MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
30" Fir	S 54 E	37.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: O.G. Timber to South, Logged to No

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE

SLOPE FACES (GIVE BEARING IN DEGREES) South ON MINUS (-) 15 %

FROM CORNER -

NORTH: + 10%

SOUTH: - 12%

EAST: About Level

WEST: About Level

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK: S 19

BY: Marion D. Hale DATE: 7-13-61
~~ENGINEER~~ - SURVEYOR

ASSISTED BY: W. Dixon
W. Cowan

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/111-12