

PUBLIC LAND CORNERS


SPRINGFIELD
SURVEY FILE

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 6 CORNER W 1/16

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

| | BEARING | FEET | ORIG. B.T. | "W" NAIL | PLATE | BRASS DISC |
|-----------|---------|------|------------|----------|-------|------------|
| 36" Cedar | S 75° E | 15.0 | -- | X | X | -- |
| | | | | | | |
| | | | | | | |
| | | | | | | |

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: O.G. South, Logged to North

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 10 E ON MINUS (-) 10 %

NORTH: + 35%

SOUTH: - 5%

EAST: + 10%

WEST: - 10% Short distance thence +

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK: S 67

BY: Martin D. Hale DATE: July 14, 1961
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: W. Dixon
W. Cowan

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: _____

CORNER _____

ACCESSORIES:

| | BEARING- | LINKS- | FEET- |
|--|----------|--------|-------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

SURVEY RECORD
DATE: _____

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____

CORNER SET: Set Hemlock Post for Corner MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

| BEARING- | FEET- | SURVEY - |
|----------|-------|----------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

PAGE 1

COPIES SENT TO: COUNTY ENGINEERS

CS 53/111-14