


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

OWNSHIP 24 S RANGE 3W
SECTION 9 CORNER N 1/4
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
26" Fir stump	N 41 E	13.1	X	X	X	--
58" Fir stump	S 51 E	33.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logging debris

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 62 W ON MINUS (-) 51 %

NORTH: +37% - 200 Ft.

SOUTH: -39% - 200 Ft.

EAST: +45% - 100 Ft.

WEST: -51% for 70 Ft. to creek 3' wide then 60% for 300' to top of a sharp ridge.

FROM CORNER 1

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Albert A. Patton DATE: May 8, 1964

ASSISTED BY: L. Thiede

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

GLO SURVEY RECORD

DATE: August 1950

CORNER 1" iron pipe with brass cap

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found cap in good condition

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
26" Fir	N 41° 45' E	27	17.8	26" Fir stump faced & scribed
18" Hemlock	S 29 1/2 W	77	50.8	Gone

Wey. Co. SURVEY RECORD DATE: 1946

PRESENT CONDITION: May 8, 1964

18" Hemlock	S 09 W	39.0'	Gone
12" Fir	N 08 W	1.6'	Gone

CORNER SET: None

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
<u>13.1 E</u>	<u>13.1</u>	<u>GLO</u>	<u>26" Fir stump with scribed face</u>

CS 53/111-15