


# PUBLIC LAND CORNERS

SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W  
SECTION 11 CORNER SE  
COUNTY Douglas OREGON



GLO SURVEY RECORD  
DATE: 1883  
CORNER Cedar Post

ACCESSORIES:

BEARING-	LINKS-	FEET-
24" Fir N 29° E	43	
20" Fir S 52° E	51	
36" Fir S 17° W	21	
18" Fir N 37° W	34	

SURVEY RECORD  
DATE: \_\_\_\_\_

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone. Found Cruiser Marks and  
Douglas Co. Appraisal Tag.

56" Fir S 17° E (Not West) 21 lks is scribed  
on bark, marked S 13 T 24 R 3 BT  
Snag stump.

PRESENT CONDITION: \_\_\_\_\_

CORNER SET: Stake for Corner MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N 47° W	22.4	GLO Fir Snag Stump
N 36° E	28.4	22" " "

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
56" Fir	S 22° E	11.8	X	X	X	
20" Cedar Snag	S 47° W	7.3		X	X	
48" Fir	N 11° W	33.2		X	X	
58" Fir	N 47° E	66.5		X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: \_\_\_\_\_  
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
SLOPE FACES (GIVE BEARING IN DEGREES) N NE ON MINUS (-) %

FROM CORNER | NORTH: \_\_\_\_\_  
SOUTH: \_\_\_\_\_  
EAST: \_\_\_\_\_  
WEST: \_\_\_\_\_

WORK DONE FOR W. T. CO.: \_\_\_\_\_ FIELD NOTES IN BOOK: Surh - 53

BY: Marion D. Hale DATE: 3-26-54  
ENGINEER - SURVEYOR

ASSISTED BY: Paul Preppernau

COPIES SENT TO: \_\_\_\_\_

UNDER THE SUPERVISION OF: \_\_\_\_\_

CS 53/11-17