

SPRINGFIELD
 SURVEY FILE

PUBLIC LAND CORNERS


WEYERHAEUSER TIMBER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 11 CORNER W 1/4

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1871

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

BEARING-	LINKS-	FEET-	
72" Fir East	15		Scribing on bark mostly gone
8" Cedar N 50 W	29		Not chopped out, some face showing but no scribing, some scribing might be inverted on part that is grown over.

WTCO. SURVEY RECORD
DATE: 6/4/1941

PRESENT CONDITION:

12" Cedar N 50 W 19.1' Tag (~~Brace~~) Tag marked S 50 W, changed to S 50 E

78" Fir East 9.9 Tag (~~Brace~~) O. K.

CORNER SET: Found Cedar stake and left it for corner MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
East	9.9	GLO WTCO.	78" Fir
N 50 W	19.1	GLO WTCO.	12" Cedar

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
36" Fir	S 66 W	23.6	-	X	X	-
56" Fir	N 53 W	35.6	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) 7/8

NORTH: _____

SOUTH: _____

EAST: _____

WEST: _____

FROM CORNER 1

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: Suth. #62 Page 13

BY: M. D. Hale DATE: 11/11/54

~~ENGINEER~~ - SURVEYOR

ASSISTED BY: R. Nice

UNDER THE SUPERVISION OF:

COPIES SENT TO: _____

SEAL PAGE 3

CS 53/111-18

13