SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 17 CORNER E 1/16 = Pt. "P" Post

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: Yew post as set in 1948 MAG. DECL.:

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
20" White Fir	S 2½° W	55.8		X	X	
22" Yew	N 45° E	3.2		X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Scattered O.G., S.G. and reproduction fir; and thick brush.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 68° E ON MINUS (–) 35 %

FROM CORNER –

NORTH: Level

SOUTH: Level

EAST: - 34

WEST: + 32

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Warren N. Hale DATE: July 19, 1961
~~ENGINEER~~ – SURVEYOR

ASSISTED BY: Cowan

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

CS 53/111-19