

See 1983  
Survey By  
Dan Baker  
M90-48

# PUBLIC LAND CORNERS


SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 22 CORNER "H" CL 1/2

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION \_\_\_\_\_

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
34" Cedar	S 22° W	4.8				
12" Fir	S 86° E	14.6				

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: \_\_\_\_\_  
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
 SLOPE FACES (GIVE BEARING IN DEGREES) \_\_\_\_\_ ON MINUS (-) %

FROM CORNER -  
 NORTH: \_\_\_\_\_  
 SOUTH: \_\_\_\_\_  
 EAST: \_\_\_\_\_  
 WEST: \_\_\_\_\_

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: \_\_\_\_\_

BY: William R. Miles DATE: 6/26/56  
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF \_\_\_\_\_

ASSISTED BY: Schultz

COPIES SENT TO: \_\_\_\_\_

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY -  
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: \_\_\_\_\_  
 CORNER None

ACCESSORIES:

BEARING-	LINKS-	FEET-

SURVEY RECORD  
 DATE: \_\_\_\_\_

PRESENT CONDITION: \_\_\_\_\_

CORNER SET: \_\_\_\_\_ MAG. DECL.: \_\_\_\_\_

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

CS 53/111-20

11