


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH



TOWNSHIP 24 S RANGE 3 W

SECTION 22 CORNER "C" N 1/6

COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: _____
 CORNER _____

ACCESSORIES:

	BEARING-	LINKS-	FEET-
NONE			

SURVEY RECORD
 DATE: _____

NONE

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____

CORNER SET: _____ MAG. DECL.: _____

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION _____

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
38" Hem.	S 82° W	15.5		X	X	
36" Cedar	N 55° E	17.9		X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) 5/16

FROM CORNER -
 NORTH: _____
 SOUTH: _____
 EAST: _____
 WEST: _____

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Hale DATE: NOT KNOWN
 ENGINEER - SURVEYOR

ASSISTED BY: Barker

COPIES SENT TO: _____

UNDER THE SUPERVISION OF _____

CS 53/111-21

21