SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 22 CORNER S 1/16 = K

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

_____ SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1" aluminum pipe by proportionate measurement MAG. DECL.:

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
22" Red Cedar	N 41° E	17.9	—	X	X	2149
48" Fir stump	N 40° W	29.8	—	X	X	2149

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: 10-20 yr. reprod.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (–) 40 %

FROM CORNER –

NORTH: Level

SOUTH: + 10%

EAST: -40%

WEST: +15%

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Glen McChesney ~~ENGINEER – SURVEYOR~~ Land Agent DATE: April 16, 1964

ASSISTED BY: Robert Barta

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/11-22