


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W
SECTION 22 CORNER W 1/4
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1871
CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
6" Fir	N 25° E	11	7.3	Gone
4" Fir	S 60° W	10	6.6	Gone

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: 1" aluminum pipe by proportionate MAG. DECL.:
measurement.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
22" Fir	N 87° E	22.0	—	X	X	#2149
16" Fir	N 52° W	41.6	—	X	X	#2149

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: 2nd growth timber

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 20 %

FROM CORNER ↓

NORTH: -5%

SOUTH: +5% 340' Post & plate on South side of road

EAST: -20%

WEST: +20%

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Alan McCreary DATE: April 16, 1964

ENGINEER - SURVEYOR
Land Agent

ASSISTED BY: Robert Barta

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL

CS 53/111-24