

PUBLIC LAND CORNERS


SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 25 CORNER S ½

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1883

CORNER Yew, Post.

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone - No evidence of original corner
was found.

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
4" Dogwood	N 18° W	38		Not found.
10" Fir	S 39° W	76		" "

Weyerhaeuser Timber Co. SURVEY RECORD
DATE: 7-6-56

PRESENT CONDITION:

24" Hem. Stump N 40° E 13.6 Plate & "W" nail.

Fair

5/8" Monel

Found steel fence post driven by
5/8" Monel pipe. M.D. Hale, June 1960

CORNER SET: 5/8" x 32" Monel pipe

MAG. DECL.: 20°

by single proportionate method.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
40" Fir Stump	S 32° E	28.7		X	X	# 243
41" Fir Stump	N 30° E	42.2		X	X	# 243

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Old Logging, Rhododendron, Reprod. Hemlock and Fir

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 50 %

NORTH: -50% 88' to SPUR 317 Sta. 19 + 50

SOUTH: +50%

EAST: About 140' to Small Creek -15%

WEST: Level along North slope

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: Suth. #67

BY: Marion D. Hale DATE: 9-1-55

~~ENGINEER~~ - SURVEYOR

ASSISTED BY: Jackmond

McDuffie

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/111-25