

# PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 245

RANGE 3W

SECTION 1

CORNER NE - Closing Corner

COUNTY Douglas

OREGON

GLO Survey Record 1894

Closing corner to Secs 1 & 6

T245 - Ranges 2 & 3 W

Set Post

No trace

60" Fir S70°E 56 lbs. 37.0'

First stump uprooted - scribing

Visible.

18" Yew S24°W 59 lbs 39.0'

20" Yew S24°W 39.0' - scribing <sup>Visible</sup>

60" Fir N37°W 32 lbs 21.1'

Nothing at this bearing and distance but found scribing

Visible on a 62" Fir stump N30°W

8.7'

Weyerhaeuser Company

Survey Record 7/19/54 by

R. Ehm & Paul Preppernaw -

Found 2 original BTs, set

1/2" G.I. Pipe and referenced

with plates & W nails:

20" Yew BT S24°W 39.0

See above - plate & "W" nail intact.

60" Fir BT N29°W 8.7

Plate & "W" nail intact - As

reported above, GLO call is

N37°W 32 lbs.

Cont'd

CONTINUED

PUBLIC LAND CORNERS - Weyerhaeuser Company - Springfield

CORNER: NE Corner (closing corner) Sec. 1-245-3W

Weyerhaeuser Company  
Survey Record-- 5/6/63  
by M. D. Hale & H. E. Case

Of original BT's found 60" Fir  
to SE blown down, 18" Yew to  
SW "OK" and indicated nothing  
found of 60" Fir BT N37°W  
32 lbs 21.1' but found a 60"  
Fir BT N29°W 8.7' as  
noted by W. Co. report of 7/19/54.

Referenced 1 new tree  
with plates & "W" nail:  
64" Fir - East - 42.8'

Reported above

" "

Reported above

64" Fir stump East 42.8'

Found 1968 Douglas County Brass cap at corner point. No new  
accessories were made, but references in effect as of 6/8/70  
with plates & "W" nails are:

50" Fir stump N30W 8.6'  
20" Yew S24W 39.0'  
64" Fir stump East 42.8'

Original BT

" "

W. Co - 5/6/63

Work Done For W. Co  
By H. E. Case - D. L. Ellis  
June 8, 1970

Reported by  
G. M. E