


# PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY  
 SPRINGFIELD BRANCH



TOWNSHIP 24S RANGE 3W

SECTION 6 CORNER SW Closing corner of Sec. 6 & 7

COUNTY Douglas OREGON

### GLO SURVEY RECORD

DATE: 1950

CORNER Brass Cap

PRESENT CONDITION -- (DESCRIBE FULLY -- USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found brass cap in good condition

### ACCESSORIES:

	BEARING-	LINKS-	FEET-
36" dia. Fir	N68°E	45	
36" dia. Fir	S62° 45' E	73	

Found, but windthrown  
Found, but windthrown

### SURVEY RECORD

DATE: \_\_\_\_\_

PRESENT CONDITION: \_\_\_\_\_

"Found in field"

16" Cedar BT N38½°W 19.3'

16" Fir BT S45°E 63.7'

"Weyerhaeuser" (1953)

40" Fir N67°E 28.4'

40" Fir S64°E 36.5'

Found with scribing visible  
Found with scribing visible

Found tags on wind thrown tree  
Found tags on wind thrown tree

CORNER SET: \_\_\_\_\_

MAG. DECL.: 20° E

### BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N38½°W	19.3		
S45°E	63.7		
N67°E	28.4	1953	
S64°E	36.5	1953	Windthrown trees

ACCESSORIES ADDED THIS DATE: 4/28/66

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
16" Cedar	N38 <sup>1</sup> / <sub>2</sub> °W	19.3	x	x	x	x
14" Hemlock	S23°W	19.6		x	x	x

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Oregon grape, salal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S10°W ON MINUS (-) 7 %

NORTH: + 8 % (6.6. chains to closing corner of Sec. 1 & 12 - 24S - 4W)

FROM CORNER |

SOUTH: - 6 %

EAST: 0 %

WEST: + 2 %

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: J.E. Shaw DATE: 4/28/66  
ENGINEER - SURVEYOR

ASSISTED BY: C. Peters

COPIES SENT TO:

UNDER THE SUPERVISION OF: