


PUBLIC LAND CORNERS

**WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH**

TOWNSHIP 24 S RANGE 2 E
 SECTION 17 CORNER E 1/4
 COUNTY DOUGLAS OREGON



GLO SURVEY RECORD

CORNER _____ DATE: _____

PRESENT CONDITION - (DESCRIBE FULLY)

ACCESSORIES:

	BEARING-	LINKS-	FEET-

SURVEY RECORD
DATE: _____

PRESENT CONDITION: _____

CORNER SET: 3" x 3" x 42" INCENSE CEDAR MAGNETIC DECLINATION: 20°
MARK POST

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-

CS 53/11-38

ACCESSORIES ADDED THIS DATE:

	BEARING -	FEET -	"W" NAIL -	PLATE -	BRASS DISC -
36" FIR	N 58° E	29.8	X	X	
22" FIR	S 20° W	49.3	X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

DESCRIPTION OF GROUND COVER AND GROUND SLOPE AT CORNER: _____

FROM CORNER NORTH: _____

SOUTH: _____

EAST: SLOPES DOWN TO THE EAST

WEST: _____

WORK DONE FOR W. T. CO.

*Field Notes in Sutherland
book No. 67*

BY: Hale Marvin De Hale
ENGINEER - SURVEYOR

DATE: JANUARY 1956

ASSISTED BY: Richard Baker

UNDER SUPERVISION OF:

COPIES SENT TO: _____

SEAL