SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W
SECTION 6 CORNER W¼
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1943
CORNER Brass Cap

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)
Found

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
8" Hemlock	N 34 E	20	13.2	8" dead Hemlock - face burned - no scribing visible.
32" Fir	S 40 E	3	2.0	36" Fir - Bark badly burned - face not opened.

WTCo. SURVEY RECORD

DATE: November 1949

PRESENT CONDITION: References below superseded December 1, 1959

Found Brass Cap - C. Price	
8" Hemlock - N36E-13.3' "W" Nail & tag BT	Tag gone - Could not see "W" nail - under log
30" Fir S40E- 1.0' " " " " BT	
WTCo. 7/24/52	
42" Fir stump - S54W - 20.3'	Found notch - no "W" nail or plate
8" Hem. BT - N37E 12.5'	Plate off
36" Fir BT - S15E - 1.0'	Found "W" nail - plate burned off

CORNER SET: Brass cap as found MAG. DECL.: 20°

This is W¼ corner Section 6 only

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY –	
N 34 E	13.4	GLO - '43	8" dead Hemlock
S 40 E	1.6	"	36" Fir

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
36" Fir	S 40 E	1.0	GLO 1943	X	X	--
42" Fir Stump	S 51 W	20.2	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Burned

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 35 E ON MINUS (–) 50 %

FROM CORNER –

NORTH: - 38% Logged to East and West

SOUTH: + 45% Logged to West, old growth to East

EAST: - 33%

WEST: + 33%

WORK DONE FOR W. T. CO.: FIELD NOTES IN BOOK:

BY: Glen McChesney DATE: December 1, 1959
~~ENGINEER – SURVEYOR~~

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/112-3