


SPRINGFIELD  
 SURVEY FILE

# PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2 W  
 SECTION 8 CORNER C 1/4  
 COUNTY Douglas OREGON



**GLO SURVEY RECORD**

CORNER \_\_\_\_\_ DATE: \_\_\_\_\_

**ACCESSORIES:**

BEARING-	LINKS-	FEET-

V. Hosford SURVEY RECORD  
 DATE: 1958

**PRESENT CONDITION:**

1 1/2" X 3/8" Iron Pipe	Found
16" Hemlock - S 42 W - 13.6'	Scribed: C 1/4 S 8 BT 255
16" Hemlock --- N 14 W - 13.6'	Scribed: C 1/4 S 8 BT 255

CORNER SET: Iron Pipe Set by Hosford Survey MAG. DECL.: 20°

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY -	
S 42 W	13.6	Hosford	Distance measured to face.
N 14 W	13.6	Hosford	Distance measured to face.

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
16" Hemlock	N 14° W	13.6	Hosford	X	X	----
62" Fir	S 2° W	27.0	Hosford	X	X	-----

**IDENTIFIED ON PHOTO:**

**INFORMATION ON LOCATION OF CORNER AS NOW SET:**

GROUND COVER: Open under old growth.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) \_\_\_\_\_ ON MINUS (-) \_\_\_\_\_ %

NORTH: 1--48% In old growth

SOUTH: - 28% In old growth

EAST: - 17% In old growth

WEST: 1 37% In old growth

FROM CORNER -

**WORK DONE FOR W. T. CO.:**

**FIELD NOTES IN BOOK:**

BY: Glenn McCreary DATE: 7/29/59

~~ENGINEER - SURVEYOR~~

ASSISTED BY: \_\_\_\_\_

COPIES SENT TO: \_\_\_\_\_

UNDER THE SUPERVISION OF \_\_\_\_\_

SEAL PAGE 3

92

CS 53/112-4