SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2 W

SECTION 8 CORNER CW 1/16 "J"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Hosford SURVEY RECORD DATE: 1958

PRESENT CONDITION:

1½" X 36" Iron Pipe	Found
24" Hemlock -- N 21½ E - 31.0'	Scribed: CW 1/16 S8 BT 253
12" Hemlock -- S 28½E -- 5.8"	Scribed: CW 1/16 S8 BT 253

CORNER SET: Iron pipe set by Hosford Survey MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 21 E	31.0	Hosford	Distance to face
S 28 E	5.0	Hosford	Distance to face

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
12" Hemlock	S 27 E	5.6	Hosford	X	X	---
48 " Fir stump 8' high	N 30 W	27.2	--------	X	X	------

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logging Debris

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 50 E ON MINUS (–) 23 %

FROM CORNER –

NORTH: + 28% old logging to west - to be logged 1959 to East

SOUTH: —12% old growth to West - to be logged 1959 to East

EAST: - 14% Old growth to South - to be logged 1959 to North

WEST: +-23% to be relogged 1959 to North and South

WORK DONE FOR W. T. CO.: FIELD NOTES IN BOOK:

BY: Glen McCluney ~~ENGINEER-SURVEYOR~~ DATE: 7/29/59

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

87

CS 53/112-5