


SPRINGFIELD
 SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W
 SECTION 8 CORNER E $\frac{1}{4}$
 COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900
 CORNER Stone marked "1"

ACCESSORIES:

BEARING-	LINKS-	FEET-	
12" Hem.	S70E	10	6.6
6" dogwood	S30 $\frac{1}{2}$ W	13	8.6

SURVEY RECORD
 DATE: _____

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found marked "1"

18" Hem-2faced not opened recently.

10"x3' dogwood stub and new 4" sprouts coming up from root.

PRESENT CONDITION: _____

CORNER SET: Original stone MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S70E	6.6	GLO	18" Hem.
S31W	8.6	GLO	Dogwood stub

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
18" Hem.	S71E	6.2	X	X	X	-
16" sugar pine	N47W	15.4	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Dogwood and Salal
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) S45W ON MINUS (-) 62 %

FROM CORNER

NORTH: 1/31% 30', -14% 30' then ascend.
 SOUTH: -54%
 EAST: 1/27% 165' rock road
 WEST: -54% 530' cr. cSouth 715' to dirt log road. tag on East side road on red cedar.

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Glen McChesney DATE: 3/24/59
~~ENGINEER SURVEYOR~~

ASSISTED BY: _____

COPIES SENT TO: _____

UNDER THE SUPERVISION OF:

SEAL PAGE 3

CS 53/112-6

23