


SPRINGFIELD  
**SURVEY FILE**

# PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W  
 SECTION 8 CORNER S $\frac{1}{4}$   
 COUNTY Douglas OREGON



**GLO SURVEY RECORD**

DATE: 1900  
 CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -  
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace

**ACCESSORIES:**

	BEARING-	LINKS-	FEET-	
8" Hem	S6W	20	13.2	14" hem. scribing visible
5" fir	N35W	21	13.9	No Trace

Vern Hosford SURVEY RECORD  
 DATE: 1958

PRESENT CONDITION:

set 1 $\frac{1}{2}$ " galv. pipe ok  
 14" h $\bar{a}$ m. scribed "S 8-25#-BT" ok

CORNER SET: found 1 $\frac{1}{2}$ " galvanized pipe MAG. DECL.: 20°

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY -
S5W	13.6	GLO
N72W	30.1	Hosford

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG.B.T.	"W" NAIL	PLATE	
14" Hem.	N72W	29.8	Hosford	X	X	
14" Hem	S4W	12.9	GLO	X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sword fern - open old growth fir

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N40E ON MINUS (-) 72 %

NORTH: -58% Old growth

SOUTH: 168% "

EAST: -36% 200' cr. c NE

WEST: 128% "

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McCleary DATE: 3/24/59  
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 2

CS 53/112-8

77