


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W
SECTION 8 CORNER SE
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900
CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Not Found

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
16" fir	N37E	53	35.0	28" fir old down tree against it faces not opened-tree leans to East
4" hem	S21E	9	5.9	8" Hem. scribing visible in upper face
4" fir	S25W	76	50.2	8" fir chopped out found scribing
4" dogwood	N45W	21	13.9	6" dogwood-scribing visible upper face- lower face not opened

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: Found 2" square stake (hub) in place MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N36E	35	GLO	28" fir
S22E	5.9	"	8" Hem
S27W	48.0	"	8" fir
N47W	13.9	"	6" dogwood

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
6" fir	N25E	54.7	-	X	X	-
8" hemlock	S27E	5.6	X	X	X	-
32" fir	S51W	47.8	-	X	X	-
38" sugar pine (school mar'm)	N23W	31.7	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Vine Maple

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 72 %

NORTH: 1 22%

SOUTH: -28% Along foot of rock bluff which ascends to North

EAST: -20% 10' then -72%

WEST: 10 / 20% then ascend rock bluff

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McCleskey DATE: 3/24/59
~~ENGINEER - SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

CS 53/112-9

CS 53/112

-9

21